









## KILTON COTTAGE CIRCA 1920




ENLARGED VIEW OF ORIGINAL VERANDAH



CONTACT: DWIGHT LANDER





FIRST FLOOR PLAN & ELEVATIONS


KILTON COTTAGE VERANDAH RESTORATION


33 OAK AVENUE PARIS ONTARIO

CONTACT: DWIGHT LANDER



P3.2.2






SECOND FLOOR PLAN & SECTIONS

KILTON COTTAGE VERANDAH RESTORATION

33 OAK AVENUE PARIS ONTARIO

CONTACT: DWIGHT LANDER






STRUCTURAL PLAN & STRUCTURAL ELEVATIONS


KILTON COTTAGE VERANDAH RESTORATION


33 OAK AVENUE PARIS ONTARIO
















SOUTH WEST CORNER COLUMN 3D VIEW

P3.2.7

**COLUMN CONNECTION 3D DETAILS** 



MORTISE IN RECESSED BEAM & NORTH END OF JOIST




**CENTRE COLUMN 3D VIEW** 


## **VERANDAH RESTORATION**

33 OAK AVENUE PARIS ONTARIO

KILTON COTTAGE



## MORTISE IN NEW BEAM & SOUTH END OF JOIST



P3.2.7

